

BIOS Release Notes

TITLE

SUBJECT: MZ73-LM1 BIOS Release Notes version R15_F39
System: MZ73-LM1-000,MZ73-LM2-000

About This Release

Build Date: 2025/03/05
BIOS Checksum: 0x721D65BE (32M)
Release Owner: Hex.Jan

BIOS Components/Contents

Processor stepping(s) supported: AMD Turin / Genoa Processors
System hardware configurations supported: MZ73-LM1-000, MZ73-LM2-000
PCB Version: 1.x,3.x
Microcode updates versions:

| CPUID | Family | Microcode Update ID |
|----------------|--------------------------|---------------------|
| Turin A0 | Family 1Ah Model 00h-0Fh | 0x0B00004D |
| Turin B0 | Family 1Ah Model 00h-0Fh | 0x0B001016 |
| Turin C0 | Family 1Ah Model 00h-0Fh | 0x0B002032 |
| Turin C1 | Family 1Ah Model 00h-0Fh | 0x0B00211E |
| Turin Dense A0 | Family 1Ah Model 00h-0Fh | 0x0B10000F |
| Turin Dense B0 | Family 1Ah Model 00h-0Fh | 0x0B101028 |

IPMI support:
AMI Kernel version: 5.35_0ACST_PI1.0.0.3_017
AGESA PI version: TurinPI 1.0.0.3
OPROM version:

| OPROM | Version |
|---------|---------|
| AST2600 | 1.13.00 |

Installation Notes

IMPORTANT NOTES:

1. Please extract the MZ73-LM1_R15_F39.zip to a bootable diskette that use FAT/FAT32 format

BIOS UPDATE INSTRUCTIONS FOR EFI Shell:

1. Insert USB flash drive to system for BIOS upgrade.
2. Power on system and boot to Build-In Shell.

BIOS Release Notes

3. Enter your USB filesystem, like "fs0:" or "fsx:", "x" is your USB filesystem number
4. Flash script for bios update:
 - 4.1 For AMD EPYC 9004 series CPU, execute f_GtoT.nsh
 - 4.2 For AMD EPYC 9005 series CPU, execute f.nsh
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE INSTRUCTIONS FOR Windows:

1. Insert bios update USB flash drive.
2. Use Command Shell.
3. For AMD EPYC 9004 series CPU:
 - 3.1 Enter \Tool\WIN\afuwin32 and execute f_GtoT.bat for Windows 32bit.
 - 3.2 Enter \Tool\WIN\afuwin64 and execute f_GtoT.bat for Windows 64bit.
4. For AMD EPYC 9005 series CPU:
 - 4.1 Enter \Tool\WIN\afuwin32 and execute f.bat for Windows 32bit.
 - 4.2 Enter \Tool\WIN\afuwin64 and execute f.bat for Windows 64bit.
5. After bios flash finish, system must Power-Off to have the changes take effect.

BIOS UPDATE FOR Easy BIOS Refresh:

1. The system supports remotely update BIOS if BMC existent.
2. Please download the Easy BIOS Refresh User Guide from Gigabyte website, target system support page.

BIOS Version CHECK INSTRUCTIONS:

1. Power on system and press during POST
2. The bios version shows on the first main page

Known Issues/Workarounds

Issues fixed in this version

R15

- 1.[Feature] Adjust the default maximum DDR speed.

R14

1. [Fix] SCE tool import/export issue.
2. [Fix] Fix Redfish sends data twice after the system has completed booting.
3. [Feature] Adjust the maximum speed limit during automatic memory training.
4. [Feature] Add support for PCIe Re-Sizeable BAR functionality.

R13

- 1.[Feature] Update AGESA 1.0.0.3.
- 2.[Feature] Support DDR speed up to 6400, but it requires manual adjustment in the BIOS settings.
UMC Common Options => Enforce POR => Accept => Memory Target Speed set [DDR6400]

BIOS Release Notes

- 3.[Fix] Fix the issue where NVMe speed is reduced to Gen4 after a hot plug.
- 4.[Fix] Fix the issue where SEL reports incorrect DDR channel information when associated with CPU1.
- 5.[Fix] Fix the issue where the system ready to boot process gets stuck when the BMC is unresponsive.

R12

1. [Feature] Update MZ73-LM2 Redriver v20241209A.

R11

- 1.[Fix] Fix usbtrees setting.

R10

- 1.[Feature] Update AGESA 1.0.0.2.
- 2.[Fix] Fix the network configuration switching issue in the BIOS Server Manager setup.
- 3.[Fix] Fix the issue where having too many installed devices causes the system to hang at the BIOS logo screen.
- 4.[Security] CVE-2024-0179, CVE-2024-21925, CVE-2024-21944, CVE-2020-10255.

R09

1. [Feature] Update MZ73-LM2 Redriver v20241022A.

R08

1. [Feature] Fixed LAN MAC Disabled fail.(Boadcom57416 lanmac show erro)
2. [Feature] Update MZ73-LM2 Redriver v20241018A.

R07

1. [Feature] Fixed MZ73-LM2 VR load fail.
2. [Feature] Prevent AC Loss send 0xF to BMC, the BMC power policy will change to always-off status.

R06

1. [Feature] Sync with Genoa solution for fix PCIe Link speed couldn't modify by bios item.
2. [Feature] AGESA 1000 NDA_Patch3 .
3. [Feature] MZ73-LM1 no sku support.

R05

BIOS Release Notes

1. [Feature]MZ73-LM1 inventory_04.
2. [AGESA]1.0.0.0 NDA
3. [Feature]Fixed Sata page on setupmenu.

R04

- 1.[Function]1.Detect VR Code Program by SKU MZ73-LM2.

R03

- 1.[Function] Add MZ73-LM2 Function.

R02

- 1.[Feture]update inventory_03.
- 2.[AGESA] 1.0.0.0 RC1.
- 3.[Feture]Fixed NMI function.
- 4.[Feture]ECC function.
5. [Project]Add MZ73-LM2 SKU.

R01

- 1.[Feature] First Release.
-